

MG Set - DC Motor to 3 Phase Alternator

Input Current

25 Amps

20 Amps

15 Amps

10 Amps

5 Amps

0 Amps

RPM

1800 RPM

1600 RPM

1400 RPM

1200 RPM

1000 RPM

800 RPM

200 Watts

400 Watts

600 Watts

800 Watts

1000 Watts

1200 Watts

1400 Watts

Generator Output Watts Calculated